#### MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS Approved by U.S. Department of Labor essentially similar to Form USHA-20 Date of prep 03-07-86 ( SECTION I SDMS DocID 548857 UNION INK COMPANY, INC. MANUFACTURER'S NAME: RIDGEFIELD, N.J. 07657 453 BROAD AVENUE ADDRESS: Superfund Records Center EMERGENCY TELEPHONE: 201-945-5766 SITE: Wells 6+H INFORMATION TELEPHONE: 201-945-5766 BREAK: 548857 OTHER: 548857 MANUFACTURERS CODE IDENTIFICATION PRODUCT CLASS: SOLVENT MIXTURE SULV-1498, LYCF-1498, LACG-1498, TRADE NAME: UNIGLAZE REDUCER UGLZ-1498, C675, PACH-1498, ETC. FABRICPATCH REDUCER REDUCER, ETC. SECTION II - HAZARDOUS INGREDIENTS I LEL I VAPOR TLV INGREDIENT I ppm I mg/M3 I I PRESSURE (gHmm) 1 f; 100 f 1 1.1 1 AROMATIC HYDROCARBON 1 1.1 1 I SØ (SKIN) GLYCOL ETHER I N.E.I STER SECTION III - PHYSICAL DATA \_ LIGHTER THAN AIR BUILING RANGE: 340-410 F. VAPOR DENSITY: X HEAVIER PERCENT VOLATILE WEIGHT PER EVAPORATION RATE: \_ FASTER X SLOWER THAN ETHER BY VOLUME: 100 GALLON: 7.5 LBS. SECTION IV - FIRE AND EXPLOSION HAZARD DATA FLAMMABILITY CLASSIFICATION: LEL: FLASH POINT: 108 F. .5 COMBUSTIBLE LIQUID EXTINGUISHING MEDIA: Use water fog-spray, carbon dioxide, dry chemicals, alcohol-type or universal-type foams applied by recommended techniques. UNUSUAL FIRE AND EXPLOSION HAZARDS: None PECIAL FIRE FIGHTING PROCEDURES: Use self contained breathing apparatus and protective clothing. 

While Union Ink believes that the data contained herein are factual and the opinions expressed are those of qualified experts regarding the results of the tests conducted, the data are not to be taken as a warranty or representation for which Union Ink assumes legal responsibity. Since the use of this information and these opinions and the conditions of use of the product are not within the control of Union Ink, it is the user's obligation to determine the conditions of safe use of the product.

K = 100KM2KM N.F. = MIT PRIARITY PRIARITY N.A. = MUT APPLICABLE

# SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE:

(SEE SECTION 11)

EFFECTS OF OVEREXPOSURE

Excessive inhalation causes headache, nausea, dizziness, vomiting, stupor, mild depression or loss of consciousness. From eye contact, irritation or burns; skin contact, drying of skin.

EMERGENCY AND FIRST AID PROCEDURES

Remove to fresh air. For breathing difficulties give artificial respiration or oxygen. Flush eyes with plenty of water for at least 15 minutes. CALL A PHYSICIAN. Wash affected skin areas with water. Remove contaminated clothing. If swallowed, do not induce vomiting.

OTHER HEALTH HAZARDS: This chemical is not considered to be carcinogenic;

Primary Route of Entry - Inhalation

# SECTION VI - REACTIVITY DATA

STABILITY: UNSTABLE  $\underline{X}$  STABLE CONDITIONS TO AVOID: Heat, sparks, open flame INCOMPATABILITY (Materials to avoid): Strong acids, alkalais, oxidizing agents HAZARDOUS DECOMPOSITION PRODUCTS: Burning may produce CO and/or CO2

HAZARDOUS POLYMERIZATION: \_ MAY OCCUR X WILL NOT OCCUR
CONDITIONS TO AVOID: None

# SECTION VII - SPILL OR LEAK PROCEDURES

اللها، مقامل اللهاء الل

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Wear suitable protective equipment. Small spills could be flushed with

large amounts of water. Large spills should be collected for disposal.

WASTE DISPOSAL METHOD:

Incinerate in a furnace where permitted under appropriate Federal, State, and local regulations.

# SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION:

Self contained or air supplied breathing apparatus in high concentrations.

VENTILATION:

Mechanical exhaust (general) is acceptable. Local exhaust is preferable to keep below TLV in work areas.

PROTECTIVE GLOVES: Use solvent resistant gloves such as neoprene or BUNA-N EYE PROTECTION: Safety Glasses, goggles, or face shields.

OTHER PROTECTIVE EQUIPMENT: Eye bath, safety shower, aprons.

HMIS INFORMATION: H.2 F.2 R.0 PP.

### SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING:

WARNING! COMBUSTIBLE
HARMFUL IF INHALED
LIQUID MAY CAUSE EYE AND SKIN IRRITATION
KEEP AWAY FROM HEAT, SPARKS, OPEN FLAME
USE ONLY WITH ADEQUATE VENTILATION

AVOID PROLONGED BREATHING OF VAPOR
OR CONTACT WITH SKIN
KEEP CONTAINER CLOSED
WASH HANDS THOROUGHLY AFTER USING

OTHER PRECAUTIONS:

FOR INDUSTRIAL USE ONLY
KEEP OUT OF THE REACH OF CHILDREN